•	Work Order Number	Work Type	Total Sub Contractor Cost with Mark-up	Total Materials Cost with Mark-up	Total Labor Cost	Total Equipment Price	Grand Total (Fees and Base Costs Totalled)
UPDT // ①	W7472686	RD-Reactive		<u>\$174.35</u>	<u>\$2321.18</u>		
UPDT // ②	W7547793	RD-Reactive			<u>\$2522.20</u>	\$300.00	\$2,822.20
UPDT // O	W7534185	RD-Reactive					
UPDT // 🍩	25790953	RD-Reactive		<u>\$358.10</u>	<u>\$2121.80</u>	<u>\$150.00</u>	A COP OF
UPDT // 🍩	W7518938	RD-Reactive		<u>\$607.37</u>	<u>\$312.12</u>		<b>&gt;</b>
UPDT // ③	W7454321	RD-Reactive		<u>\$6229.56</u>	<u>\$3638.71</u>		
NEW // ②	W7559265	RD-Reactive					
NEW // ②	W7559666	RD-Reactive			<u>\$104.04</u>		
UPDT // ②	W7429611	RD-Reactive	<u>\$1497.27</u>		<u>\$4473.72</u>		(
UPDT // O	W7542471	RD-Reactive					<b>,</b>
UPDT // O	W7536192	RD-Reactive			<u>\$520.20</u>		<b>&gt;</b>
UPDT Ø 👁	C218404	RD-Reactive			<u>\$416.16</u>		<b>/</b>
UPDT // O	W7535055	RD-Reactive		<u>\$36.04</u>	<u>\$504.44</u>	<u>\$37.50</u>	
UPDT // ①	W7510369	RD-Reactive		<u>\$1617.76</u>	<u>\$9100.17</u>		
UPDT // ①	W7549939	RD-Reactive					
	W7553862	RD-Reactive		<u>\$344.04</u>	<u>\$416.16</u>		
	W7529086	RD-Reactive		<u>\$47.90</u>	<u>\$624.24</u>		
	W7413801	RD-Reactive	<u>\$3352.80</u>	<u>\$944.50</u>	<u>\$1988.86</u>		
	C207402	RP-Reactive Project		<u>\$406.90</u>	\$2949.68	\$338.70	\$3,695.29
	C209718	PJ-Planned Job		<u>\$136.29</u>	\$1603.02	<u>\$84.67</u>	\$1,823.99
	C210360	RP-Reactive Project		<u>\$538.14</u>	<u>\$1871.59</u>	<u>\$338.70</u>	\$2,748.43
	W7515017	RD-Reactive		<u>\$88.44</u>	<u>\$936.36</u>		
	W7539124	RD-Reactive			<u>\$104.04</u>		
	W7534971	RD-Reactive			\$208.08		
I							
				Not tota	aling left to		
				right un	less		
					ent Price		
I				Presen	t		